



Landing Overruns- Human Factors



Captain David Oliver

General Manager Flight Technical

Qantas Airways Limited



Landing Overruns - Human Factors

A review of the events leading to, and lessons learnt from the over-run of flight QF1 at Bangkok Thailand, September 23, 1999.



Landing Configuration

- Operating Boeing 747-400 since 1989
- Standard landing configuration up until 1996 was “Flap 30, Full Reverse Thrust”



Landing Configuration

(continued)

- Review of landing configuration was undertaken due to:
 - Noise levy at Sydney
 - ✓ Flap 25 chosen for lower noise, better fuel economy
 - Carbon Brake Wear
 - ✓ Idle reverse thrust chosen for less noise and longer, harder brake application



Landing Configuration

(continued)

- Landing configuration Policy from late 1996 was:
 - Flap 25, idle reverse thrust *provided* the runway length was not limiting



The Landing

- F/O was pilot flying
- The runway was wet
 - The last landing airplane had reported “good” braking action
 - The airplane preceding QF1 executed a Missed Approach due to poor visibility in heavy rain
 - This was not relayed to the crew of QF1



The Landing

(continued)

- Airplane crossed the threshold high and fast (but within Company limits) and “floated” 10ft above the runway in heavy rain
- Within a period of just a few seconds:
 - The Captain called for “Go- Around”
 - The main gear touched down
 - The rain eased and visibility improved
 - Captain reached over and took control of the thrust levers



The Landing

(continued)

- The Captain initially only retarded # 2, 3 and 4 Thrust Levers
- The F/O immediately realized this and retarded #1 to idle, however:
 - With main gear on the ground and # 1 or 4 T/L advanced, the autobrakes disarmed
 - Speedbrakes deployed automatically after #1 T/L was retarded by the F/O



The Landing

(continued)


- The EICAS message “AUTOBRAKES” was not initially noticed by the Flight Crew
- Manual braking was not applied until 8 seconds after touchdown, approx 5000 feet down the runway
- No reverse thrust was applied for the whole of the landing roll




The Landing

(continued)

- When manual braking was applied
NO deceleration was felt
- Both pilots exerted maximum force on the
brake pedals, still with no deceleration
– *The airplane was aquaplaning*
- The airplane only began to decelerate as it
entered the last 1000 feet of the runway and
the groundspeed reduced below 110kts



Comparison of rollout deceleration on various runway surfaces and VH-OJH 23 September 1999



Ambient conditions:
 OAT 25 deg C
 QNH 1013.2
 WIND 3.6 kt HWC

— 23 Sep BKK — Dry Rwy — Contam Rwy (Good brkg) — Contam Rwy (Poor brkg)

Aircraft configuration for various runway surfaces:
 * 252,000 kg Vref25 + 5 kts
 * Maximum manual braking
 * Spoilers deployed, Idle forward thrust



Human Factors

- Why did this happen ?
- Accident analysis showed:
 - A number of significant active failures and
 - Significant inadequate defences



Active Failures

- The runway was affected by water
- Flight Crew failed to use an appropriate risk management strategy for the approach and landing
- The F/O did not fly the aircraft accurately during final approach
- The Flight Crew were confused over who had control and did not select appropriate level of reverse thrust




Inadequate Defences

- Company published information, procedures and training for landing on water affected runways was inadequate
- Flight Crew training in evaluating the procedural and configuration options for approach and landing was deficient
 - The crew may have been “pre-conditioned” to the use of Flap 25 and idle reverse thrust



Change Management

- Published the Boeing document “Landing on Slippery Runways” (doc D6-44247) in the Qantas Flying Manual
- Provided a flow chart to assist Flight Crew in determining appropriate flap and reverse thrust settings





Change Management

(continued)

- Flight Crew use max reverse thrust as the “standard” with idle reverse permitted only under stipulated conditions
- Flap 25 is the normal landing flap on dry runways
- Flap 30 used on wet runways (no credit taken for grooving or PFC overlay)



Change Management

(continued)

- Produced CBT package summarising performance on slippery and contaminated runways
- Provided detailed stopping distance information for various surface conditions
- Highlighted to crew the importance of using correct techniques for landing on wet, slippery and contaminated runways
- Included call of “AUTOBRAKES” each time this is annunciated on EICAS




Change Management

(continued)

- Monitoring of landing configurations and touchdown points has shown:
 - Significant trend towards flap 30 irrespective of runway conditions
 - Max. reverse thrust used on most occasions
 - Touchdown points are closer to the “desired” point. i.e. less “float”




Trend in Landing Flap Setting






Trend in Reverse Thrust Use





Trend in Distance From 50' to TD





Cabin Communications

- Nose gear collapse resulted in loss of all Flight Deck / Cabin communications
- Confusion existed as to need for evacuation
- Co-location of back-up comms equipment in an area prone to damage is considered undesirable
- Provided Flight and Cabin Crew with procedures to use in the event of loss of Cabin Interphone or PA



Summary

- Provide Flight Crew with the appropriate tools to do the job
- Train Flight Crew to analyse each landing separately to determine the appropriate landing configuration
- Ensure procedures for landing on wet, slippery and contaminated runways are in place and thoroughly understood
- ATSB report available at www.atsb.gov.au