


**ADVANCES IN**

# **VOLCANIC ASH**

**AVOIDANCE AND RECOVERY**



A commercial airplane encounter with volcanic ash can threaten safety of flight because of resulting conditions that range from windshield pitting to loss of thrust in all engines. Developments in technology and communication networks have significantly decreased the probability of such an encounter in the last several years. Despite these developments, however, a 737-700 recently flew through a volcanic ash cloud. Updated information about advancements made in ensuring safe operations and minimizing damage to the airplane during a volcanic ash encounter is now available to flight crews.

AERO

19

## SAFETY

THOMAS J. CASADEVALL, PH.D.  
DEPUTY DIRECTOR  
U.S. GEOLOGICAL SURVEY

THOMAS M. MURRAY  
SAFETY ENGINEERING ANALYST  
AIRPLANE PERFORMANCE  
AND PROPULSION  
BOEING COMMERCIAL  
AIRPLANES GROUP

In the past 30 years, more than 90 jet-powered commercial airplanes have encountered clouds of volcanic ash and suffered damage as a result. The increased availability of satellites and the technology to transform satellite data into useful information for operators have reduced the number of volcanic ash encounters. However, further coordination and cooperation, including linking operators and their dispatchers to the network of government volcano observers, is required throughout the industry. Boeing has always advocated that flight crews avoid volcanic ash clouds or exit them immediately if an encounter occurs. The company also recommends specific procedures for flight crews to follow if they cannot avoid an encounter.

Flight crews will be better prepared to avoid volcanic ash clouds and take the appropriate actions during an encounter if they understand the following information:

1. Results of past events involving volcanic ash.
2. Resources available to help avoid ash encounters.
3. Specific flight crew actions required in response to encounters.

## 1 RESULTS OF PAST EVENTS INVOLVING VOLCANIC ASH

Significant ash encounters from the past include those involving such well-known volcanoes as Mt. Pinatubo, Mt. Redoubt, and Mt. St. Helens. The airplanes that encountered volcanic ash during these events and in the other events listed chronologically experienced varying degrees of damage.

### **Mt. St. Helens, United States, 1980.**

A 727 and a DC-8 encountered separate ash clouds during this major eruption. Both airplanes experienced damage to their windshields and to several systems, but both landed safely despite the windshield damage.

### **Galunggung volcano, Indonesia, 1982.**

Several 747s encountered ash from this eruption. One airplane lost thrust from all four engines and descended from 36,000 ft to 12,500 ft before all

four engines were restarted. The airplane, on a flight from Kuala Lumpur, Malaysia, to Perth, Australia, diverted to Jakarta and landed safely despite major engine damage. This airplane subsequently had all four engines replaced before returning to service. A few days after the initial encounters, another 747 flew into the ash cloud and suffered significant engine damage. This airplane also diverted to Jakarta and subsequently performed a successful two-engine landing.


### **Mt. Redoubt, United States, 1989.**

On a flight from Amsterdam to Anchorage, Alaska, a new 747-400 (only three months old with approximately 900 hr total flying time) encountered an ash cloud from the erupting Mt. Redoubt near Anchorage. All four engines ingested ash and flamed out. The crew successfully restarted the engines and landed safely at Anchorage.


All four engines were replaced and many airplane systems also had to be repaired or replaced. For example, the airplane environmental control system was replaced (see below), the fuel tanks were cleaned, and the hydraulic systems were repaired. Several other airplanes encountered ash from this eruption, but most damage was minor because operators had been notified of the eruption. Some operators, such as Alaska Airlines, continued scheduled flights once they developed processes to safely identify where ash might be encountered. Although information was available about the Mt. Redoubt eruption, the channels for sharing this information were not well developed at the time (see "Alaska Airlines Procedures for Operating in Volcanic Ash Conditions" on p. 25).

### **Mt. Pinatubo, Philippines, 1991.**


More than 20 volcanic ash encounters occurred after the Mt. Pinatubo eruption, which was the largest volcanic eruption of the past 50 years. The ability to predict where ash was to be found was challenging because of the enormous extent of the ash cloud. Commercial flights and various military operations were affected; one U.S.



Engine damage from ash ingestion




Environmental control system damage



Electrical panel damage






Geostationary operational environmental satellite detection and tracking of volcanic ash cloud from an eruption of Bezymianny volcano, Russia, that began at 7:00 a.m. on Feb. 24, 1999. The red triangle indicates the volcano location. Highest ash concentrations are indicated in orange and yellow. The blue areas on 0000Z and 0800Z are noise and do not indicate ash. The cloud was tracked at 15-min increments for 1,500 km until it dispersed beyond the limits of detection.

In addition to providing VAASs directly to the airlines, the VAACs also provide information to appropriate meteorological organizations that subsequently issue significant meteorological information (SIGMET) and other reports. The ICAO publication "International Airways Volcano Watch" (ICAO annex III) contains further information and contact names and numbers. Detailed information on the VAACs, including contacts for each of the nine centers, is available at <http://www.ssd.noaa.gov/VAAC/>.

Operators rely on the VAACs for information, and many operators maintain direct contact with volcano observatories within their flight domains. For instance, the Alaska Volcano Observatory (AVO) in Anchorage, with links to Fairbanks, issues a weekly bulletin by e-mail and fax detailing the activity of key volcanoes in Alaska. During periods of volcanic unrest and eruption, bulletins are

issued frequently as conditions change. Anyone can request to be placed on distribution for the bulletins. The AVO web site (<http://www.avo.alaska.edu/>) also provides updated information. For those without Internet access or unable



Reports can indicate whether the activity is steam, as shown above, or ash.

Right: Geologists from the AVO examine fresh pyroclastic flow from Mt. Redoubt, Mar. 23, 1990.

to access the site if it is overloaded during a crisis, the AVO daily telephone recording at 907-786-7477 provides brief updated information for air carriers. Finally, many operators maintain personal relationships with individuals in the volcano observatories that monitor volcanoes within a particular flight domain. For instance, Alaska Airlines maintains contact with key individuals at the AVO because a significant portion of Alaska's flight domain could be affected by Alaskan volcanoes.

Many other web sites provide information and links to other sources of volcano information (see "Volcanic Ash Resources" on p. 27). A wealth of printed information, such as the *Bulletin of the Global Volcanism Network* through the Smithsonian National Museum of Natural History in Washington, D.C., is also available. However, the information about current volcanic activity in these printed sources is often two to three months old.



Despite ongoing avoidance efforts, operators can still experience volcanic ash encounters. Guidance on the operational issues surrounding volcanic ash is divided into three aspects: avoidance, recognition, and procedures. The following information is general; flight crews should refer to their respective company's operating manuals for details.

### Avoidance.

Preventing flight into potential ash environments requires planning in these areas:

- Dispatch needs to provide flight crews with information about volcanic events, such as potentially eruptive volcanoes and known ash sightings, that could affect a particular route (see sidebar at bottom of p. 26).
- Dispatch also needs to identify alternate routes to help flight crews avoid airspace containing volcanic ash.
- Flight crews should stay upwind of volcanic ash and dust.
- Flight crews should note that airborne weather radar is ineffective for distinguishing ash and small dust particles.

### Recognition.

Indicators that an airplane is penetrating volcanic ash are related to odor, haze, changing engine conditions, airspeed, pressurization, and static discharges.

- **Odor.** When encountering a volcanic ash cloud, flight crews usually notice a smoky or acrid odor that can smell like electrical smoke, burned dust, or sulfur.
- **Haze.** Most flight crews, as well as cabin crew or passengers, see a haze develop within the airplane. Dust can settle on surfaces.
- **Changing engine conditions.** Surging, torching from the tailpipe, and flameouts can occur. Engine temperatures can change unexpectedly, and a white glow can appear at the engine inlet.
- **Airspeed.** If volcanic ash fouls the pitot tube, the indicated airspeed can decrease or fluctuate erratically.

- **Pressurization.** Cabin pressure can change, including possible loss of cabin pressurization.
- **Static discharges.** A phenomenon similar to St. Elmo's fire or glow can occur. In these instances, blue-colored sparks can appear to flow up the outside of the windshield or a white glow can appear at the leading edges of the wings or at the front of the engine inlets.

### Procedures.

The following nine procedures are general recommendations. Each operator's flight operations manuals will include more specific directions.

1. **Reduce thrust to idle immediately.** By reducing thrust, engines may suffer less buildup of molten debris on turbine blades and hot-section components. Idle thrust allows engines to continue producing electrical power, bleed air for pressurization, and hydraulic power for airplane control.
2. **Turn the autothrottles off.** This prevents the engines from increasing thrust above idle. Ash debris in the engine can result in reduced surge margins, and limiting the number of thrust adjustments improves the chances of engine recovery.
3. **Exit the ash cloud as quickly as possible.** A 180-deg turn out of the ash cloud using a descending turn is the quickest exit strategy. Many ash clouds extend for hundreds of miles, so assuming that the encounter will end shortly can be false. Climbing out of the ash could result in increased engine debris buildup as the result of increased temperatures. The increased engine buildup can cause total thrust loss.
4. **Turn on engine and wing anti-ice devices and all air-conditioning packs.** These actions improve the



engine stall margins by increasing the flow of bleed air.

5. **If possible, start the auxiliary power unit (APU).** The APU can power systems in the event of a multiple-engine power loss. It can also be used to restart engines through the use of APU bleed air.
6. **If volcanic dust fills the flight deck, the crew may need to use oxygen.** Use flight deck oxygen at the 100 percent setting. Manual deployment of the passenger oxygen system is not required because it will deploy automatically if the cabin altitude exceeds 14,000 ft.
7. **Turn on the continuous ignition.** Confirm that autostart is on, if available. In the event that the engines flame out or stall, use appropriate procedures to restart the engines. During restart, the engines may take longer than normal to reach idle thrust due to the combined effects of high altitude and volcanic ash ingestion. If an engine fails to start, try restarting it again immediately. Flight crews should remember that the airplane may be out of the airstart envelope if the encounter occurs during cruise.
8. **Monitor engine exhaust gas temperature (EGT).** Because of potential engine debris buildup, the EGT can climb excessively. The flight crew should prevent EGT exceedances. Shut down the engine and restart it if the EGT is approaching limits similar to a hung start.
9. **Fly the airplane by monitoring airspeed and pitch attitude.** If necessary, follow the procedure for flight with unreliable airspeed.



## SUMMARY

Though the number of commercial airplane encounters with volcanic ash clouds has decreased significantly over the past several years, the potential for this type of event still exists. Efforts to advance knowledge about how to avoid and recover from these encounters have resulted in improved capability in these areas. By working with members of the volcanological community, the aviation industry has developed procedures to share information about events with flight crews, dispatchers, volcano scientists, and others. Volcano observatories that provide daily updates through e-mail messages or phone recordings have been established. In addition, a variety of Internet sources provide information that operators can tailor to their specific flight domains. Finally, flight operations procedures are documented and available to flight crews to help them respond immediately and appropriately to maintain the highest possible level of flight safety.

**A**laska Airlines has many active volcanoes within its flight domain. To prepare for an eruption and resulting encounter with volcanic ash, the airline has developed focused guidelines for flight operations when eruptions interfere with its route structures:

1. When in doubt, don't fly.
2. Use facts and data.
3. Identify the location of both the ash and clear areas.
4. Stay focused.



## **1** WHEN IN DOUBT, DON'T FLY

The fundamental principle by which Alaska Airlines operates is knowing where to find the ash after a volcanic eruption. If unsure of the ash location, it will not allow its flight crews to fly through the eruption area. Though this approach is conservative, Alaska Airlines successfully and safely operated after the 1989 Mt. Redoubt eruption and other volcanic eruptions.

## **2** USE FACTS AND DATA

Alaska Airlines has selected several information sources, uses Volcanic Ash Advisory Statements from the Volcanic Ash Advisory Centers, and is in direct communication with the Alaska Volcano Observatory. During a major eruption, Alaska Airlines will interview its own pilots as well as other operators' pilots about their observations on ash location. It has also established contacts on the ground that it can call for additional intelligence. These individuals include mayors and police officers in villages and towns near the airline's flight paths. If Alaska Airlines receives inconsistent information, it double-checks and continually validates what appears to be correct.



## **3** IDENTIFY THE LOCATION OF BOTH THE ASH AND CLEAR AREAS

Alaska Airlines tracks the ash by asking a number of questions:

- Where is the ash itself?
- Where is the volcanic source of the ash?
- What are the winds doing?
- What information is available from the volcanological community?
- What information do the reports from the pilots, selected contacts, and others contain?

Alaska Airlines then provides its pilots with information on where to fly and the reasons for not flying in certain areas.

## **4** STAY FOCUSED

Ed Haeseker, manager of air traffic control for Alaska Airlines, worked during the Mt. Redoubt event with Tom Cufley, then chief pilot at Alaska Airlines. They found that a small team worked better than a large team, especially if the chief pilot provided information directly to the flight crew in the early days of the event. In addition, a small team can travel more quickly to the site where the greatest assistance is needed and remain focused on the key task: identifying where the ash is.

## ICAO ACTIVITIES ON VOLCANIC ASH

The International Civil Aviation Organization (ICAO) initiated a volcanic ash effort in 1982 after multiple

volcanic ash encounters by 747 airplanes near Jakarta, Indonesia. The resulting organization, the Volcanic Ash Warnings Study Group, has worked since then to standardize the information provided to flight crews about volcanic eruptions.

In addition, ICAO formed the International Airways Volcano Watch (IAVW) in 1987. This effort formalized the international arrangements for monitoring and providing warnings to airplanes about volcanic ash in the atmosphere. ICAO annex III and the World Meteorological Organization (WMO) Technical Regulation C.3.1 introduced a requirement to disseminate information about volcanic ash to airplanes in the form of significant meteorological information (SIGMET) and notice to airmen (NOTAM).

The first WMO/ICAO workshop on volcanic ash hazards was held in Darwin, Australia, in 1995. Since then, a number of the designated Volcanic Ash Advisory Centers (VAAC) have come into full operation. A second workshop in Toulouse, France, in 1998 focused primarily on VAAC responsibilities and procedures

More information about ICAO activities related to volcanic ash avoidance and encounters is available in the organization's document titled "Operational Procedures And List Of Operational Contact Points Between Vulcanological Agencies, Meteorological Watch Offices And Area Control Centres," or from the address to the right.

**T. Fox**

**Secretary of the ICAO Volcanic Ash Warnings Study Group**

**Chief - Meteorology**

**International Civil Aviation Organization**

**999 University Street**

**Montreal, Quebec H3C 5H7 Canada**

**E-mail: tfox@icao.org**

## VOLCANO ERUPTION WARNING COLOR CODES

Eruption warnings are issued in the form of color-coded information releases. Over the past 10 years, this method has proved to be effective for alerting the aviation community to potential volcanic ash.

ALERT COLOR CODE	VOLCANO ACTIVITY STATUS
Red	Volcanic eruption in progress. Ash plume or cloud reported above FL 250.
	Volcano dangerous, eruption likely, with ash plume or cloud expected to rise above FL 250.
Orange	Volcanic eruption in progress but ash plume or cloud not reaching nor expected to reach FL 250.
	Volcano dangerous, eruption likely, but ash plume or cloud not expected to reach FL 250.
Yellow	Volcano known to be active from time to time and volcanic activity has recently increased significantly, volcano not currently considered dangerous but caution should be exercised.
	After an eruption, i.e., change in alert to yellow from red or orange, volcanic activity has decreased significantly, volcano not currently considered dangerous but caution should be exercised.
Green	Volcanic activity considered to have ceased and volcano reverted to its normal state.

The responsible volcanological agency in the region where the volcano erupts should provide the area control center with (1) the color code for the level of alert indicating the status of activity of the volcano and (2) any change from a previous status of activity (e.g., "Red alert following yellow" or "Green alert following orange"). Source: ICAO—International Airways Volcano Watch.

## VOLCANIC ASH RESOURCES

Volcanic ash resources are available worldwide and in many forms

accessible to operators. Volcano observatories are located throughout the world, including the Alaska Volcano Observatory for information about North Pacific volcanoes and the Nordic Volcanological Institute for information about volcanic activity that could affect North Atlantic routes. Many of these observatories provide immediate eruption and volcanic ash updates to operators by fax, e-mail, telephone, or teletype. Information is also available on the World Wide Web at the following sites:

**The Smithsonian National Museum of Natural History Global Volcanism Program:** <http://www.volcano.si.edu/gvp/>

**The U.S. Geological Survey:** <http://www.usgs.gov/themes/volcano.html>

**The Airline Dispatcher Federation (a detailed paper about volcanic ash written by Leonard J. Salinas of United Airlines, Chicago, Illinois):**  
<http://www.dispatcher.org/library/VolcanicAsh.htm>

**The Committee on Earth Observation Satellites Disaster Management Support Project/Volcanic Hazards Management (an effort by the U.S. National Oceanic and Atmospheric Administration; information on tracking ash clouds):**

**The Istituto Internazionale di Vulcanologia (a summary of volcanoes in Italy):** <http://www.iiv.ct.cnr.it/>

**The Nordic Volcanological Institute (information about volcanoes in and around Iceland):** <http://www.norvol.hi.is/index.html>

**The Volcanological Society of Japan (eruption information, live images of Japanese volcanoes, and other information):**  
<http://hakone.eri.u-tokyo.ac.jp/kazan/VSJ1E.html>

**Current Eruptions in Japan (additional current information):**  
<http://hakone.eri.u-tokyo.ac.jp/vrc/erup/erup.html>

**Other sources of information include the following:**

The Boeing Company, *Airliner* magazine ("Vulcan's Blast," April-June 1990, and "Vulcan Returns: Volcanic Ash Effects on Airplanes Revisited," October-December 1991) and video ("Volcanic Ash Avoidance: Flight Crew Briefing").

U.S. Federal Aviation Administration, *Aviation Safety Journal* reprint ("The Volcano Threat to Aviation Safety").

Casadevall, T. J., ed. 1994. The First International Symposium on Volcanic Ash and Aviation Safety: Proceedings Volume: U.S. Geological Survey Bulletin 2047.

Casadevall, T. J., T. B. Thompson, and T. Fox. 1999. World map of volcanoes and principal air navigation features. U.S. Geological Survey Map I-2700.

THE PRIMARY SOURCE FOR ANY VOLCANIC ERUPTION AND ASH INFORMATION IS A VOLCANIC ASH ADVISORY CENTER. THE OTHER SOURCES LISTED HERE MAY OFFER MORE DETAILED INFORMATION ON A PARTICULAR ERUPTION. – ED.